



TEST REPORT

Report No. :BJ-R221208104A-EN

Test Item :Load bearing test

Client :Lu'an Arlott Composite Materials Technology Co., Ltd.

Address :No. 184, South Zhengyang Road, Jin'an District
Lu'an City, Anhui Province, China

ShenZhen BestJ Testing Technologies Co., Ltd

Inspected Engineer: Lu Yuehui

Date: Dec.12,2022

Reviewed Engineer: Luo Ningsheng

Date: Dec.12,2022

Authorized Signatory: Zhang Jianbiao

Date: Dec.12,2022



Content

1.SAMPLE INFORMATION	2
2.TEST INFORMATION	2
3.TEST RESULTS	2
4.Load bearing test	3
4.1 Reference Standard	3
4.2 Laboratory Environment	3
4.3 Test Equipment	3
4.4 Test Procedure	3
4.5 Test Conditions	3
4.6 Test Photos	4

1.SAMPLE INFORMATION

Sample Name	Garage Floor Tiles
Sample Model	400*400*18mm
Sample No.	BJ-R221208104A-1#
Sample Size	/
Weight Of Sample	/
Sample Quantity	1 PC
Manufacturer	/
Address	/
Sample Source	Commissioned units send sample
Inspection Type	Commissioning test
Sample Description	Sample appearance is good

2.TEST INFORMATION

Test Items	Received Date	Date Of Test(s)
Load bearing test	Dec.08,2022	Dec.09,2022

3.TEST RESULTS

Test Items	Test Results
Load bearing test	The sample can withstand 8T pressure without damage.

4. Load bearing test

4.1 Reference Standard

Test according to customer's test requirements

4.2 Laboratory Environment


Ambient temperature: $25 \pm 3^{\circ}\text{C}$

Relative humidity: $55 \pm 20\% \text{RH}$

4.3 Test Equipment

Test Equipment	Equipment Model	Calibration Date
Tensile testing machine	BE-XL-8TS	Apr 19, 2022

4.4 Test Procedure




4.5 Test Conditions

Test weight: 8 tons, positive pressure.

4.6 Test Photos


Before test



Test setup



After test



Test curve

